

Vehicle Condition Report Vehicle VIN: 5TFDW5F13BX174393

Vehicle Information



**Year :** 2011  
**Brand :** Toyota  
**Model :** Tundra 4WD Truck  
**Body Type :** Pickup  
**Drive Type :** Four Wheel Drive  
**Engine :** 5.7L 381.0hp  
**Transmission :** Automatic  
**Mileage :** 134,500  
**Exterior Color :**  
**Interior Color :** Gray  
**Doors :** 4


Details:  
 Used vehicle Automotive


Condition Report

Exterior	Interior	Mechanical	
<ul style="list-style-type: none"> <li>• Front Bumper</li> <li>• Front Gille</li> <li>• Glass</li> <li>• Hood</li> <li>• Left Doors</li> <li>• Left Front Fender</li> <li>• Left Rear</li> <li>• Paint</li> <li>• Rear Bumper</li> <li>• Right Doors</li> <li>• Right Front Fender</li> <li>• Right Rear</li> <li>• Trunk</li> </ul>	★★★★★	<ul style="list-style-type: none"> <li>• Carpet</li> <li>• Dash</li> <li>• Electronics</li> <li>• Front Seats</li> <li>• Headliner</li> <li>• Rear Seats</li> </ul>	★★★★★
		<ul style="list-style-type: none"> <li>• Air Conditioning</li> <li>• Brakes</li> <li>• Engine</li> <li>• Exhaust</li> <li>• Steering</li> <li>• Suspension</li> <li>• Tires</li> <li>• Transmission</li> </ul>	★★★★★

**Date :** 15 Dec 2018                      **Signature :** \_\_\_\_\_

Vehicle Pictures





Visit our website at [walkerautosalesllc.com](http://walkerautosalesllc.com) or Call Us (225) 202-6777