

Vehicle Condition Report **Vehicle VIN: SCBBR93W278043045**

Vehicle Information



Year : 2007
Brand : Bentley
Model : Continental Flying Spur
Body Type : Sedan
Drive Type : All Wheel Drive
Engine : 6.0L 552.0hp
Transmission : Manual
Mileage : 29,000
Exterior Color :
Interior Color :
Doors : 4

Details:

Welcome to **ALL WHEELS AUTOMOTIVE**,
 Your **CEDAR HILL DEALER**.

Our clients have high expectations for their vehicles, and equally high expectations about the dealership professionals who serve them. **ALL WHEELS AUTOMOTIVE** is widely recognized to be among the best in quality, reliability, value and customer satisfaction in both sales and service.

When you're ready, come on by for a test drive!

Condition Report

Exterior

- Front Bumper
- Front Gille
- Glass
- Hood
- Left Doors
- Left Front Fender
- Left Rear
- Paint
- Rear Bumper
- Right Doors
- Right Front Fender
- Right Rear
- Trunk

★★★★★

Interior

- Carpet
- Dash
- Electronics
- Front Seats
- Headliner
- Rear Seats

★★★★★


Mechanical

- Air Conditioning
- Brakes
- Engine
- Exhaust
- Steering
- Suspension
- Tires
- Transmission

★★★★★

Date : 17 Jan 2019 **Signature :** _____

Vehicle Pictures





Visit our website at www.allwheelsautomotives.com or Call Us 972-291-5929