

Vehicle Condition Report

Vehicle VIN: 1G1PE5SB4F7195041

Vehicle Information

Year : 2015

Brand : Chevrolet

Model : Cruze

Body Type : Sedan

Drive Type : Front Wheel Drive

Engine : 1.4L 138.0hp


Transmission : Automatic

Mileage : 46,323

Exterior Color : Gray

Interior Color :

Doors : 4



Details:

Welcome to ALL WHEELS AUTOMOTIVE,  
Your CEDAR HILL DEALER.


Our clients have high expectations for their vehicles, and equally high expectations about the dealership professionals who serve them. **ALL WHEELS AUTOMOTIVE** is widely recognized to be among the best in quality, reliability, value and customer satisfaction in both sales and service.

*When you're ready, come on by for a test drive!*

Condition Report


Exterior

- Front Bumper
- Front Gille
- Glass
- Hood
- Left Doors
- Left Front Fender
- Left Rear
- Paint
- Rear Bumper
- Right Doors
- Right Front Fender
- Right Rear
- Trunk
- Wheels




Interior

- Carpet
- Dash
- Electronics
- Front Seats
- Headliner
- Rear Seats



Mechanical

- Air Conditioning
- Brakes
- Engine
- Exhaust
- Steering
- Suspension
- Tires
- Transmission



Date : 28 Mar 2024

Signature :

Vehicle Pictures





Visit our website at [allwheelsautomotives.com](http://allwheelsautomotives.com) or Call Us 972-291-5929